

2450DM41A5400

Nomor bagian:	2450DM41A5400
Pabrikan / Merek:	Johanson Technology
Deskripsi Produk	RF DIPLEXER MODULE
Lembar data:	
Status RoHs	 Berisi timbal / RoHS tidak patuh
Kirim Dari	Hongkong
Cara pengiriman	DHL/Fedex/TNT/UPS/EMS


[PERMINTAAN KUTIPAN](#)

Gambar bisa berupa representasi. Lihat spesifikasi untuk detail produk.













Spesifikasi 2450DM41A5400

NOMOR BAGIAN	2450DM41A5400
PABRIKAN	Johanson Technology
DESKRIPSI	RF DIPLEXER MODULE
MEMIMPIN STATUS BEBAS / STATUS ROHS	Berisi timbal / RoHS tidak patuh
LEMBARAN DATA	
SERI	*
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
STATUS GRATIS MEMIMPIN / STATUS ROHS	Contains lead / RoHS non-compliant
DETIL DESKRIPSI	RF Diplexor

Tag terkait

Johanson Technology 2450DM41A5400	Distributor 2450DM41A5400	Pemasok 2450DM41A5400
Harga 2450DM41A5400	Gambar 2450DM41A5400	Gambar 2450DM41A5400
Lembar Data PDF 2450DM41A5400	2450DM41A5400 Unduh Lembar Data	Lembar Data 2450DM41A5400
Stok 2450DM41A5400	Beli 2450DM41A5400	Beli Johanson Technology 2450DM41A5400
Johanson Technology 2450DM41A5400	Pemasok Johanson Technology	Distributor Johanson Technology
Johanson Technology 2450DM41A5400	Johanson 2450DM41A5400	Johanson Technology Inc. 2450DM41A5400

 Produk-produk
terkait

 <p>2450DM40A1575E Produsen: Johanson Technology Deskripsi: RF DIPLEXER 1.575GHZ/2.45GHZ Persediaan: 702 pcs</p> <p>RFQ</p>	 <p>2450CMG86980002 Produsen: Honeywell Sensing and Productivity Solutions Deskripsi: MANUAL RESET THERMOSTAT Persediaan: Out stock</p> <p>RFQ</p>
 <p>2450CP05A5400T Produsen: Johanson Technology Deskripsi: RF DIPLEXER 0202 4 LEAD Persediaan: Out stock</p> <p>RFQ</p>	 <p>2450CMN80821029 Produsen: Honeywell Sensing and Productivity Solutions Deskripsi: MANUAL RESET THERMOSTAT Persediaan: Out stock</p> <p>RFQ</p>
 <p>2450DP15E5400E Produsen: Johanson Technology Deskripsi: RF DIPLEXER 2.45GHZ/5.4GHZ 1206 Persediaan: Out stock</p> <p>RFQ</p>	 <p>2450DP15F5400E Produsen: Johanson Technology Deskripsi: RF DIPLEXER 2.45GHZ/5.4GHZ 0805 Persediaan: Out stock</p> <p>RFQ</p>
 <p>2450DP15G5400E Produsen: Johanson Technology Deskripsi: RF DIPLEXER 2.45GHZ/5.4GHZ 0805 Persediaan: Out stock</p> <p>RFQ</p>	 <p>2450CMG81840033 Produsen: Honeywell Sensing and Productivity Solutions Deskripsi: MANUAL RESET THERMOSTAT Persediaan: Out stock</p> <p>RFQ</p>
 <p>2450CMG82090129 Produsen: Honeywell Sensing and Productivity Solutions Deskripsi: MANUAL RESET THERMOSTAT Persediaan: Out stock</p> <p>RFQ</p>	 <p>2450DP15A5512E Produsen: Johanson Technology Deskripsi: RF DIPLEXER 2.45GHZ/5.51GHZ 0805 Persediaan: Out stock</p> <p>RFQ</p>
 <p>2450DP15B5512E Produsen: Johanson Technology Deskripsi: RF DIPLEXER 2.45GHZ/5.51GHZ 0805 Persediaan: Out stock</p> <p>RFQ</p>	 <p>2450DP15D5400E Produsen: Johanson Technology Deskripsi: RF DIPLEXER 2.45GHZ/5.4GHZ 0805 Persediaan: Out stock</p> <p>RFQ</p>